Digital Barometric Pressure Sensor

High accuracy and small size barometric pressure sensor with low current consumption

- Measure barometric pressure and temperature with high accuracy
- Built in low noise 24 bit ADC
- Digital control and output via I²C/SPI interface
- Automatically power down non-working circuit to minimize power consumption
- Individual calibration parameters stored in OTP*
 * One Time Programmable ROM

RoHS compliant

Application Example

- Indoor navigation (floor detection)
- Car navigation (to distinguish highway and frontage road)
- Altimeter
- Activity monitor (to detect up and down of stairs)
- Life log
- Weather forecast

Target Devices Example

- Smart Phones / Tablet PCs
- Wearable devices, such as watch type, band type, clip type or glasses type
- GPS devices
- Pedometer

Packaging Information

Standard Models with Surface Mounting Terminals

	U		
Structure	Packaging	Model	Minimum Packing Unit
LGA 9 pin	Tape and Reel	2SMPB-02E	3,500



Table of Contents Application Example1

Packaging Information ■ Standard Models with Surface Mounting Terminals	
Table of Contents	2
Ratings / Specifications / Function	
Use conditions and recommended operating conditions	
Absolute Maximum Ratings	
■ Operating Ratings ■ Electrical Characteristics	
Digital Interface Characteristics	
 Characteristics by Oversampling setting (Forced Mode) Image: ms Noise by IIR Filter Selection 	
-	
■ Bandwidth by IIR Filter Selection	
■ Filter selection based on use cases	
Connection	5
Block Diagram	5
Pin Description and Layout	5
■ Typical Connection Diagram	6
Dimensions	7
■ Package	
■ Cutline Dimension	
■ Outline Dimension	
■ Marking structure	
Operations	
Communication Mode	
■ Communication mode	
■ Power Mode	
■ Implementing Register List	
SPI Protocol	
■ SPI Protocol	
■ Interface specifications	
■ Recommended conditions of communication	
Packaging	17
■ Configuration of shipment	17
Taping	17
Reel	18
■ Individual packaging	18
Recommended Soldering Method	19
Soldering method	19
Condition of Temperature	19
Recommended Soldering Method	19
Safety Precautions	20
Warranty and Limited Warranty	
· · · · · · · · · · · · · · · · · · ·	· - ·

Ratings / Specifications / Function

Use conditions and recommended operating conditions

Type of Pressure	Absolute pressure
Medium	Air *
Operating Pressure Range	30 kPa to 110 kPa

* Never use corrosive gases.

Absolute Maximum Ratings

Item	Symbol	Rating	Unit	Remark
Power Supply Voltage	Vddmax	4.0	V	
Input Voltage (other than power)	Vmax	-0.2 to Vopr+0.2	V	
Maximum Pressure	Pmax	800	kPa	
Storage Temperature	Tstr	-40 to 85	°C	with no condensation or icing
Storage Humidity	Hstr	10 to 95	%RH	with no condensation or icing
ESD (HBM)	Vhbm	±2000	V	
ESD (MM)	Vmm	±200	V	
ESD (CDM)	Vcdm	±500	V	

Operating Ratings

Item	Symbol	Min.	Тур.	Max.	Unit	Remark
Operating Voltage	Vopr	1.71	1.8	3.6	V	VDD
	Vio	1.20	1.8	3.6	V	VDDIO
Operating Temperature	Topr	-40	-	85	°C	

Electrical Characteristics (At Ta = 25°C, VDD = 1.8 V, unless otherwise noted)

Item	Symbol	Condition	Min.	Тур.	Max.	Unit
Average Current	lhp	1 sample/s Forced Mode Ultra High Accuracy	-	21.4	-	μA
Operating Current Consumption	lddp	Pressure mode	-	640	800	μA
Operating Current Consumption	lddt	Temperature mode	-	410	520	μA
Sleep Mode Current Consumption	Isleep		-	1.1	2.3	μA
Measureable Pressure Range	Popr		30	-	110	kPa
	Pabs1	30 to 110 kPa, 0 to 65°C	-	±50	-	Pa
Absolute Pressure Accuracy	Pabs2	30 to 110 kPa, -20 to 0°C	-	±80	-	Ра
Relative Pressure Accuracy	Prel1	Ultra High Accuracy	-	±3.9	-	Pa
rms Noise	Pnois	Ultra High Accuracy	-	1.3	-	Pa
Absolute Temperature Accuracy	Tabs	30 to 110 kPa, -20 to 65°C	-2	-	2	°C
Pressure Resolution	Pres		-	0.06	-	Pa
Temperature Resolution	Tres		-	0.0002	-	°C
Power Supply Rejection Ratio (DC)	Ppsrr	101.3 kPa, 0 to 40°C, 1.71 to 3.6 V Base on VDD = 1.8 V	-9.4	-	9.4	Pa

Note: 1. Typical specifications are not guaranteed.

Note: 2. The above table shows the characteristics of the Package before soldering.

Digital Interface Characteristics (At Ta = 25°C, VDD = 1.8 V, unless otherwise noted)

Item	Symbol	Condition	Min.	Тур.	Max.	Unit
Digital Input Low Voltage	Vil_d		-	-	Vio×0.2	V
Digital Input High Voltage	Vih_d		Vio×0.8	-	Vio+0.2	V
Digital Input Hysterisis Voltage	Vidhys		Vio×0.1	-	-	V
Digital Output Low Voltage (I ² C)	Vol_d1	lo = 3 mA (SDI) *	0	-	Vio×0.2	V
Digital Output Low Voltage (SPI)	Vol_d2	lo = 1 mA (SDI, SDO) *	0	-	Vio×0.2	V
Digital Output High Voltage1 (SPI) (Vio >= 1.62 V)	Voh_d1	lo = 1 mA (SDI, SDO) *	Vio×0.8	-	-	v
Digital Output High Voltage2 (SPI) (Vio >= 1.2 V)	Voh_d2	lo = 1 mA (SDI, SDO) *	Vio×0.6	-	-	v
Leakage Current at Output OFF	loff	SDI, SDO	-10	-	10	μA
Internal Pullup Resistor	Rpullup	CSB	70	120	190	kΩ
I ² C Load Capacitance	Cb	SDI, SCK	-	-	400	pF
Load Capacitance of Reset Terminal	Crst		-	-	20	pF
Pulse Width of Asynchronous Reset	Trst		100	-	-	µsec
Power On Startup Time	Tstart		-	-	10	msec

* "lo" is the load current of the output terminal.

Note: Undescribed items are compliant with the I²C specification.

About detailed I²C bus information, please refer to the I²C bus specification and user manual presented by NXP.

■ Characteristics by Oversampling setting (Forced Mode)

(At Ta = 25°C, VDD = 1.8 V, CPU Clock Frequency = 300 kHz, unless otherwise noted)

Oversampling setting	Pressure oversampling	Temperature oversampling	Measurement time Typ.	ODR @ standby 1 ms Typ.	Average Current Typ. @ 1 sample/sec Forced Mode	rms Noise Typ.
unit	-	-	msec	Hz	μA	Pa
High speed	2	1	5.5	153	4.1	5.2
Low power	4	1	7.2	121	5.2	3.7
Standard	8	1	10.6	86	7.3	2.6
High accuracy	16	2	18.3	51	12.0	1.8
Ultra High accuracy	32	4	33.7	28	21.4	1.3

Note 1: These characteristics are guaranteed by design.

Note 2: ODR is defined as Output data rate at standby time 1 msec.

■ rms Noise by IIR Filter Selection (At Ta = 25°C, VDD = 1.8 V, unless otherwise noted)

			Typical rms Noise	e in Pressure [Pa]		
Oversampling setting	IIR filter coefficient					
	off	2	4	8	16	32
High speed	5.2	2.5	1.6	1.1	0.8	0.5
Low power	3.7	1.8	1.1	0.8	0.5	0.4
Standard	2.6	1.3	0.8	0.5	0.4	0.3
High accuracy	1.8	0.9	0.6	0.4	0.3	0.3
Ultra High accuracy	1.3	0.6	0.4	0.3	0.3	0.2

Note 1: IIR; Infinite impulse response

Note 2: These characteristics are guaranteed by design.

Note 3: Initial setting of the IIR filter coefficient is "off".

■ Bandwidth by IIR Filter Selection (At Ta = 25°C, VDD = 1.8 V, unless otherwise noted)

			Typical Ban	idwidth [Hz]		
Oversampling setting	Oversampling setting IIR filter coefficient					
	off	2	4	8	16	32
High speed	153.0	35.3	14.7	6.8	3.3	1.6
Low power	121.0	28.0	11.6	5.4	2.6	1.3
Standard	86.0	19.9	8.3	3.8	1.8	0.9
High accuracy	51.0	11.8	4.9	2.3	1.1	0.5
Ultra High accuracy	28.0	6.5	2.7	1.2	0.6	0.3

Note 1: These characteristics are guaranteed by design.

Note 2: Initial setting of the IIR filter coefficient is "off".

■ Filter selection based on use cases (At Ta = 25°C, VDD = 1.8 V, unless otherwise noted)

		Pressure over	Temp. over		Specificat	ion (Typ.)	
Example use case	Oversampling setting	sampling times	sampling times			ODR [Hz] (Example)	rms Noise [Pa]
Weather monitoring	High speed	×2	×1	off	1.2	0.05	5.2
Drop detection	Low power	×4	×1	off	407	100	3.7
Elevator detection	Standard	×8	×1	4	63.4	10	0.8
Stair detection	High accuracy	×16	×2	8	219	20	0.4
Indoor navigation	Ultra high accuracy	×32	×4	32	570	28	0.2

Note: These characteristics are guaranteed by design.

Connection

Block Diagram



Pin Description and Layout



Top View

Pin No.	Symbol	Desci	ription	
Pill No.	Symbol	SPI	I ² C	
1	RST	Asynchronous Res	set *1	
2	CSB	CSB	VDDIO	
3	SDI	SDI/SDO	SDA	
4	SCK	SCK	SCL	
5	SDO	SDO	ADDR	
6	VDDIO	Power Terminal for	Digital IO	
7	GND	Ground Terminal		
8	VDD	Power Terminal		
9	VPP	NVM Writing Term	inal *2	



Bottom View

*1. If you do not need the reset function, please just have the layout design of PCB of connecting both No. 1 (RST) pin and No. 7 (GND) pin into the ground of PCB. Please refer "■ Reset Function" for the case of using the reset function.

*2. Pin 9 is only used internally in OMRON. Please leave the pin disconnected.

If Pin 9 is connected with any other Pin electrically, the sensor will not work properly.

Typical Connection Diagram

I²C mode (Corresponding to 100 Kbit/s (at Standard Mode), 400 Kbit/s (at Fast Mode) and 3.4 Mbit/s (at High Speed Mode))



4-wire SPI mode (Corresponding to 10 Mbit/s)



2SMPB-02E

3-wire SPI mode (Corresponding to 10 Mbit/s)



Dimensions (Unit: mm)

Package

Package Type: LGA (Land Grid Array) 9 pin Package Size: $2.00 \times 2.50 \times 0.85$ mm Material of the terminal surface: Au

Outline Dimension



Mounting PAD Dimensions Recommended (Top View)



Marking structure



Operations

Communication Mode

This sensor is corresponding to I^2C and SPI communication.

Digital interface terminal functions for each communication mode are as below.

Communication Mode	CSB	SDI	SCK	SDO	Remark
I ² C	VDDIO	SDA	SCL	GND/VDDIO	SDO = GND \rightarrow 70h, SDO = VDDIO \rightarrow 56h
SPI 3 Wires	CSB	SDI/O	SCK	-	spi3w Register = 1
SPI 4 Wires	CSB	SDI	SCK	SDO	spi3w Register = 0

When changing the communication mode, also see Typical Connection Diagram section.

- I²C mode becomes effective by pulling CSB up to VDDIO.
- SPI mode becomes effective by pulling CSB down to GND.
- Once CSB is pulled down, SPI mode would not be changed unless otherwise Power on Reset (POR) or Asynchronous Reset. Switching between SPI 3-Wire mode and SPI 4-Wire mode can be configured with the register value of "spi3w". Refer to IO_SETUP register section for more detail.
- Default mode after POR or Asynchronous Reset will be I²C mode.

Power Mode

This sensor has three power modes and it can be switched by setting CTRL_MEAS register.

Refer to the "CTRL_MEAS" register section for more detail.

- Sleep Mode
- Normal Mode
- Forced Mode

Transition diagram for each mode is as follows.



Sleep Mode (Power Reduction Mode)

No measurements are performed.

I²C/SPI interface and each register can be accessed even if the sensor is in Sleep Mode.

Forced Mode

In case of Forced Mode, a single measurement is performed. When the set up measurement is finished, the sensor returns to Sleep Mode after storing the measurement data to the register.



Normal Mode

In case of Normal Mode, the measurements are performed repeatedly between a measurement period and a standby period. The standby time can be configured by "t_stanby[2:0]" register. Be sure to consider that the data must be read from the master side after a Normal Mode.



Compensation of Pressure and Temperature

This section describes a typical measurement procedure and a calculation method after POR. This sensor has compensation coefficients in internal Non Volatile Memory (NVM). The compensated pressure can be calculated by using these values.



MSB of PRESS_TXDx, TEMP_TXDx and COE_** are sign bit.

- (1) Configure IO mode setting. Refer to IO_SETUP register section for more detail.
- (2) Read compensation coefficients which are stored in NVM. This procedure is sufficient just once after POR. These values are used for a compensation calculation at the step (6) and (7).
- (3) Configure averaging times and power mode. Refer to CTRL_MEAS register section for more detail.
- (4) Read raw temperature data which are stored in TEMP_TXDx registers.
- (5) Read raw pressure data which are stored in PRESS_TXDx registers.
- (6) Compensated temperature can be calculated by using the below formula and the values of the step (2) and (4).

$Tr = a0 + a1 \bullet Dt + a2 \bullet Dt^2$

Tr: Calculation Result of Temperature (Tr/256 = Temperature [degree C]) e.g.) If Tr Value is 6400 LSB,

Temperature (degree C) = $\frac{\text{Tr Value (LSB)}}{\text{Scaling Factor}} = \frac{6400 \text{ LSB}}{256 \text{ LSB/degree C}} = 25.00 \text{ degree C}$

- Dt: Raw Temperature Data [digit] (20-24bits measurement value of TEMP_TXDx Reg.)
- a0: Compensation Coefficient of PTAT (NVM resister: COE_a0_ex, COE_a0_0, COE_a0_1)
- a1: Compensation Coefficient of PTAT (NVM resister: COE_a1_0, COE_a1_1)
- a2: Compensation Coefficient of PTAT (NVM resister: COE_a2_0, COE_a2_1)

(7) Correction pressure without temperature compensation can be calculated by using the below formula and the values of the step (2) and (6).

 $Pr = b00 + bt1 \bullet Tr + bp1 \bullet Dp + b11 \bullet Dp \bullet Tr + bt2 \bullet Tr^{2} + bp2 \bullet Dp^{2}$ $+ b12 \bullet Dp \bullet Tr^{2} + b21 \bullet Dp^{2} \bullet Tr + bp3 \bullet Dp^{3}$

- Pr: Calculation Result of Pressure [Pa]
- Tr: Calculation Result of Temperature (Tr/256 = Temperature [degreeC])
- Dp: Raw Pressure Data [digit] (20-24bits measurement value of PRESS_TXDx Reg.)
- b00 : Compensation Coefficient of Pressure (NVM resister: COE_b00_ex, COE_b00_0, COE_b00_1)
- bt1 : Compensation Coefficient of Pressure (NVM resister: COE_bt1_0, COE_bt1_1)
- bp1: Compensation Coefficient of Pressure (NVM resister: COE_bp1_0, COE_bp1_1)
- b11: Compensation Coefficient of Pressure (NVM resister: COE_b11_0, COE_b11_1)
- *bt2* : Compensation Coefficient of Pressure (NVM resister: COE_bt2_0, COE_bt2_1)
- bp2 : Compensation Coefficient of Pressure (NVM resister: COE_bp2_0, COE_bp2_1)
- b12 : Compensation Coefficient of Pressure (NVM resister: COE_b12_0, COE_b12_1)
- *b21* : Compensation Coefficient of Pressure (NVM resister: COE_b21_0, COE_b21_1)
- bp3 : Compensation Coefficient of Pressure (NVM resister: COE_bp3_0, COE_bp3_1)

How to get compensation coefficients

Each compensation coefficients can be calculated by using the below formula and conversion factors.

$K = A + \frac{S \times OTP}{32767}$ a1, a2, bt1, bt2, bp1, b11, bp2, b12, b21, bp3	V OTP
$K = A + \frac{32767}{32767}$ a1, a2, bt1, bt2, bp1, b11, bp2, b12, b21, bp3	$K = \frac{16}{16}$ a0, b00
52707	10

ĸ	Conversi	on factor	OTP							
	А	S	23-16 bit	15-8 bit	7-0 bit					
a1	-6.3E-03	4.3E-04	-	COE_a1_1	COE_a1_0					
a2	-1.9E-11	1.2E-10	-	COE_a2_1	COE_a2_0					
bt1	1.0E-01	9.1E-02	-	COE_bt1_1	COE_bt1_0					
bt2	1.2E-08	1.2E-06	-	COE_bt2_1	COE_bt2_0					
bp1	3.3E-02	1.9E-02	-	COE_bp1_1	COE_bp1_0					
b11	2.1E-07	1.4E-07	-	COE_b11_1	COE_b11_0					
bp2	-6.3E-10	3.5E-10	-	COE_bp2_1	COE_bp2_0					
b12	2.9E-13	7.6E-13	-	COE_b12_1	COE_b12_0					
b21	2.1E-15	1.2E-14	-	COE_b21_1	COE_b21_0					
bp3	1.3E-16	7.9E-17	-	COE_bp3_1	COE_bp3_0					

к	Conversion factor		OTP	
	Conversion nacion	19-12 bit	11-4 bit	3-0 bit
a0	Offset value (20Q16)	COE_a0_1	COE_a0_0	COE_a0_ex
b00	Offset value (20Q16)	COE_b00_1	COE_b00_0	COE_b00_ex

Implementing Register List

			9.0.0		1			<u> </u>						
Register Name	Add I ² C	ress SPI	Length	R/W	bit7 bit6	bit5	bit4	Data bit3	a bit2	bit1	bit0	Descriptions	Initial	
TEMP_TXD0	FCh	7Ch	8bit	R/-				t_txd0[]	7:0]			Temperature DATA [8:1] in 24 bits	00h	
TEMP_TXD1	FBh	7Bh	8bit	R/-				t_txd1[]	7:0]		Temperature DATA [16:9] in 24 bits			
TEMP_TXD2	FAh	7Ah	8bit	R/-				t_txd2[7	7:0]	Temperature DATA [24:17] in 24 bits *	00h			
PRESS_TXD0	F9h	79h	8bit	R/-				p_txd0[Pressure DATA [8:1] in 24 bits	00h				
PRESS_TXD1	F8h	78h	8bit	R/-				Pressure DATA [16:9] in 24 bits	00h					
PRESS_TXD2	F7h	77h	8bit	R/-				p_txd2[Pressure DATA [24:17] in 24 bits *	00h				
IO_SETUP	F5h	75h	8bit	R/W	t_stanby[2:0] - spi3_sdim - spi3w					t_stanby[2:0] : Standby time setting spi3w : SPI mode setting (4 or 3 wire) spi3_sdim : Select output type of SDI terminal	00h			
CTRL_MEAS	F4h	74h	8bit	R/W	temp_avera	np_average[2:0] press_average[2:0] power_mode[1:0] p p				temp_average[2:0] : Temperature Averaging Times press_average[2:0] : Pressure Averaging Times power_mode[1:0] : Power mode setting	00h			
DEVICE_STAT	F3h	73h	8bit	R/-		-	-	measure	-	-	otp_update	measure : Status of measurement otp_update : Status of OTP data access	00h	
I ² C_SET	F2h	72h	8bit	R/W		-	-	-	mast	er_co	de[2:0]	Master code setting at I ² C HS mode	01h	
IIR_CNT	F1h	71h	8bit	R/W	filter[2:0]						IIR filter co-efficient setting	00h		
RESET	E0h	60h	8bit	W	reseti / 10							When inputting "E6h", a software reset will be occurred.	00h	
CHIP_ID	D1h	51h	8bit	R/-				chip_id[7:0]			CHIP_ID : 5Ch	5Ch	
COE_b00_a0_ex	B8h	38h	8bit	R/-	b0	0[3:0]			a0[3	:0]		Compensation Coefficient	-	
COE_a2_0	B7h	37h	8bit	R/-	a2[7:0]						Compensation Coefficient	-		
COE_a2_1	B6h	36h	8bit	R/-	a2[15:8]							Compensation Coefficient *	-	
COE_a1_0	B5h	35h	8bit	R/-				a1[7:0	D]			Compensation Coefficient	-	
COE_a1_1	B4h	34h	8bit	R/-				a1[15:	:8]			Compensation Coefficient *	-	
COE_a0_0	B3h	33h	8bit	R/-				a0[11:	4]			Compensation Coefficient	-	
COE_a0_1	B2h	32h	8bit	R/-				a0[19:	12]			Compensation Coefficient *	-	
COE_bp3_0	B1h	31h	8bit	R/-				bp3[7:	:0]			Compensation Coefficient	-	
COE_bp3_1	B0h	30h	8bit	R/-				bp3[15	:8]			Compensation Coefficient *	-	
COE_b21_0	AFh	2Fh	8bit	R/-				b21[7:	:0]			Compensation Coefficient	-	
COE_b21_1	AEh	2Eh	8bit	R/-				b21[15	:8]			Compensation Coefficient *	-	
COE_b12_0	ADh	2Dh	8bit	R/-				b12[7:	:0]			Compensation Coefficient	-	
COE_b12_1	ACh	2Ch	8bit	R/-				b12[15	:8]			Compensation Coefficient *	-	
COE_bp2_0	ABh	2Bh	8bit	R/-				bp2[7:	:0]			Compensation Coefficient	-	
COE_bp2_1	AAh	2Ah	8bit	R/-				bp2[15	:8]			Compensation Coefficient *	-	
COE_b11_0	A9h	29h	8bit	R/-								Compensation Coefficient	-	
COE_b11_1	A8h	28h	8bit	R/-	b11[15:8] Compensation Coefficient *							Compensation Coefficient *	-	
COE_bp1_0	A7h	27h	8bit	R/-		bp1[7:0] Compensation Coefficient							-	
COE_bp1_1	A6h	26h	8bit	R/-				bp1[15				Compensation Coefficient *	-	
COE_bt2_0	A5h	25h	8bit	R/-				bt2[7:	01			Compensation Coefficient	-	
COE_bt2_1	A4h	24h	8bit	R/-				bt2[15	-			Compensation Coefficient *	-	
COE_bt1_0	A3h	23h	8bit	R/-				bt1[7:	-			Compensation Coefficient	_	
COE_bt1_1	A2h	22h	8bit	R/-				bt1[15	-			Compensation Coefficient *	_	
COE b00 0	A1h	21h	8bit	R/-				b00[11				Compensation Coefficient	_	
COE_b00_1	A0h	20h	8bit	R/-							_			
		TEM		,									1	

* MSB of PRESS_TXDx, TEMP_TXDx and COE_** are sign bit.

TEMP(PRESS)_TXDx : Temperature and Pressure data : TXD0, TXD1 or TXD2

This sensor holds ADC data with 22 to 24 bits accuracy. It can be obtained as each 24 bits data. If there are redundant data, the low order positions will be filled by zero (0). The shaded regions as shown below are valid data area.

bit	24	23	22	 5	4	3	2	1	Note		
22 bits output	D21	D20	D19	 D2	D1	D0	0	0	Temp/Press_ave = 001		
23 bits output	D22	D21	D20	 D3	D2	D1	D0	0	Temp/Press_ave = 010		
24 bits output	D23	D22	D21	 D4	D3	D2	D1	D0	Temp/Press_ave = 011 to 111		

Note: 1. Dn (D23 to D0) : Sensor Data The value of n bit (1 or 0)

Note: 2. The raw measurement values are unsigned 24 bits values. The values need to do subtraction with 2²³ at 24 bits output mode. Here is a programing example for Dt and Dp calculation.

Dt = ((TEMP_TXD2) <<16) + ((TEMP_TXD1) << 8) + (TEMP_TXD0) - pow(2,23) Dp = ((PRESS_TXD2) <<16) + ((PRESS_TXD1) << 8) + (PRESS_TXD0) - pow(2,23)

IO_SETUP : IO SETUP Register

Register Name	I ² C Addr.	SPI Addr.	Length	R/W	bit7	bit6	bit5	bit4	bit3	bit2	bit1	bit0	initial
IO_SETUP	F5h	75h	8bits	R/W	t_stanby[2:0]		-	-	spi3_sdim	-	spi3w	00h	
bit7 to 5 t stanby[2:0] : Standby time setting													

05	I_stanby[2:0] : Standby time setting												
	000	001	010	011	100	101	110	111					
	1 ms	5 ms	50 ms	250 ms	500 ms	1 s	2 s	4 s					

bit3 to 4 Reserved : keep these bits at 0

bit2 spi3_sdim : Select output type of SDI terminal

0 : Lo / Hi-z output (Default)

bit1 Reserved : keep this bit at 0

spi3w : Change mode between SPI 4-wire and SPI 3-wire

0 : 4-wire (Default)

1 : 3-wire

bit0

2SMPB-02E

CTRL_MEAS : Measurement Condition Control Register

• · · · ·							g.e.e.								
Register	Name	I ² C Addr.	SPI Ac	ddr. Le	ngth	R/W	bit7	bit6	bit5	bit4	bit3	bit2	bit1	bit0	initial
CTRL_ME	AS	F4h	74h	ı 8	8bits R/W		temp_average[2:0]				press_average[2:0]			power_mode[1:0]	
bit7 to 5	temp	_average[2	2:0]	Averaging times setting for Temperature measurement (skip means no me								asureme	ent.)		
				000	001	01	0	011	100	101	110	111			
				skip	1	2	2	4	8	16	32	64			
bit4 to 2 press_average[2:0] Averaging times setting for Pressure measurement (skip means no measurement									irement.)						
				skip	1	2		4	8	16	32	64			
bit1, 0	powe	power_mode[1:0] Operation mode setting 00 : Sleep Mode 01, 10 : Forced Mode 11 : Normal Mode													

DEVICE_STAT : Device Status Register

				-										
Register N	Name	I ² C Addr.	SPI Addr.	Length	R/W	bit7	bit6	bit5	bit4	bit3	bit2	bit1	bit0	initial
DEVICE_S	TAT	F3h	73h	8bits	R	-	1	_	-	measure	-	_	otp_update	00h
bit7 to 4	Rese	rved : keep	o these bits	at 0										
bit3	meas	sure	re Device operation status. This value automatically changes.											
		0: Finish a measurement waiting for next measurement												
			1:	1: On a measurement waiting for finishing the data store										
bit2, 1	Rese	rved : keej	ep these bits at 0											
bit0	otp_u	ıpdate	The status of NVM data access. This value automatically changes.											
			0:	No acc	essing N	VM data	а							
1: While accessing NVM data														

^{1 :} Lo / Hi output

I²C_SET : Master code setting

		-											
Register Name	I ² C Addr.	SPI Addr.	Length	R/W	bit7	bit6	bit5	bit4	bit3	bit2	bit1	bit0	initial
I ² C_SET	F2h	72h	8bits	R/W	-	-	-	-	-	m	aster_cod	le[2:0]	01h

bit7 to 3	Reserved : keep these bits at 0
-----------	---------------------------------

bit2, 1, 0 master_code[2:0]

Master code setting at I²C high-speed mode.

		0	0 1				
000	001	010	011	100	101	110	111
08h	09h	0Ah	0Bh	0Ch	0Dh	0Eh	0Fh

IIR_CNT : IIR filter co-efficient setting Register

Register Name	I ² C Addr.	SPI Addr.	Length	R/W	bit7	bit6	bit5	bit4	bit3	bit2	bit1	bit0	initial
IIR_CNT	F1h	71h	8bits	R/W	-	-	-	-	-	f	ilter[2:0]		00h

bit7 to 3 Reserved : keep these bits at 0 bit2, 1, 0

IIR filter co-efficient setting filter[2:0]

Write access to this register address, IIR filter will be initialized.

Note: Initial setting of the IIR filter coefficient is "off".



000	001	010	011	100	101	110	111
OFF	N = 2	N = 4	N = 8	N = 16	N = 32	N = 32	N = 32

RESET : Reset Control Register

Register Name	I ² C Addr.	SPI Addr.	Length	R/W	bit7	bit6	bit5	bit4	bit3	bit2	bit1	bit0	initial
RESET	E0h	60h	8bits	W	reset[7:0]					00h			
bit7 to 0 reset[7:0] When input "E6h", the software reset will be effective.													

Except for that, nothing is to happen.

CHIP_ID : Chip ID Confirmation Register

···· _·-	· • ···r													
Register	Name	I ² C Addr.	SPI Addr.	Length	R/W	bit7	bit6	bit5	bit4	bit3	bit2	bit1	bit0	initial
CHIP_ID		D1h	51h	8bits	R				chip	_id[7:0]				5Ch
bit7 to 0	chip_	_id[7:0]	5Cł	า										

2SMPB-02E

I²C Protocol

(1) I²C Slave Address

The 2SMPB-02 module I²C slave address is shown below.

500	SDO I ² C Slave Address (7 bits)	Bit	bit7	bit6	bit5	bit4	bit3	bit2	bit1	bit0
300	1-C Slave Address (7 bits)	Dit	Add[6]	Add[5]	Add[4]	Add[3]	Add[2]	Add[1]	Add[0]	R/W
High (1)	56h + R/W	Value	1	0	1	0	1	1	0	1/0
Low (0)	70h + R/W	Value	1	1	1	0	0	0	0	1/0

For example, in case of SDO = Low (0),

Write Access : Please set LSB of slave address as "0", then the address is E0h (1110_0000b). (70h<<1+WR(0)) Read Access : Please set LSB of slave address as "1", then the address is E1h (1110_0001b). (70h<<1+RD(1))

(2) I²C Access Protocol Examples

Symbol	Condition
START	START condition
STOP	STOP condition
SACK	Acknowledge by Slave
MACK	Acknowledge by Master
MNACK	Not Acknowledge by Master

(3) Register Write Access Protocol

After the START condition, a Device Address is sent. This address is seven bits long followed by an eighth bit which is a data direction bit. A 'zero' indicates a transmission "WRITE". After that, the register address and the writing data shall be one set and it should be continuously transmitted until a STOP condition. A data transfer is always terminated by a STOP condition generated by the master.



Black characters: Master --> Slave / Blue characters: Slave --> Master

(4) Register Read Access Protocol

After a START condition, the Device Address with WRITE sign ("0") and Word Address intended to read a first data are transmitted. Next, "STOP-START" or "Re-START" condition are transmitted by the master. After that, Device Address with READ sign ("1") is transmitted by the master. Then, the slave will output the first data that is intended to read. In case of incrementing Register Address automatically, the slave will output the data repeatedly until NACK is input by the master. If Register Address becomes "FFh", please continue to output "00h". Below example shows 3 bytes reading method from "FAh" register.



SPI Protocol

(1) SPI write

"SPI Write" needs to transmit the one set data of Register Address (Ctl.="0"+Address) and a writing data in the situation where CSB is "L". Two or more writing can be possible during CSB is "L". If CSB becomes "H", SPI communication will finish. (as well as I²C write)

CSB																
SCK		\sim	<u> </u>				\checkmark	\sim	<u></u>		\checkmark	\checkmark		\checkmark	` `	$\sqrt{-}$
SDI/O	Start	0	Address (7	/bit)	Wr	ite Data (8bit)	0	Ad	ddress (7	7bit)	V	Vrite Data	(8bit)		Stop

(2) SPI read

First, "SPI read" needs to transmit Register Address (Ctl.="1"+Address) in a situation where CSB is "L".

Next, the data of the requested register address will be output from SDO. (in case of 3-wire mode, the data will be output from SDI). After that, the register address is automatically incremented by one until CSB becomes "H", the device will output the data repeatedly. (as well as I²C read)

Below shows an example of the 2 bytes reading from "FAh" register.



■ Interface specifications

(1) I²C timings

All timings apply to 100 kbps (at Standard Mode), 400 kbps (at Fast Mode) and 3.4 Mbps (at High Speed Mode). For I²C timings, the following abbreviations are used :

S&F Mode = Standard and Fast Mode

Cb = bus capacitance on SDI line

HS Mode = High Speed Mode

All other naming refers to I²C specification 2.1 (January 2000).



Undescribed items and symbols are compliant with the I²C specification.

Items	Symbol	Condition		Min.	Тур.	Max.	Units	Remark
		S&F Mode		160	-	-	ns	
SDI setup time	t _{SUDAT}	HS Mode	Vio = 1.62 V	30	-	-	ns	
		HS Mode	Vio = 1.2 V	55	-	-	ns	
		S&F Mode, $Cb \le 100 \text{ pF}$		80	-	-	ns	
	S&F Mode, $Cb \le 400 \text{ pF}$		90	-	-	ns		
SDI hold time	t	HS Mode, $Cb \leq 100 \text{ pF}$	Vio = 1.62 V	18	-	115	ns	
SDI Hold time	t _{HDDAT}		Vio = 1.2 V	25	-	140	ns	
		HS Mode, Cb ≤ 400 pF	Vio = 1.62 V	24	-	150	ns	
		10 Mode, 00 3 400 pi	Vio = 1.2 V	45	-	170	ns	
SCK low pulse	t	HS Mode, Cb ≤ 100 pF	Vio = 1.62 V	160	-	-	ns	
CONTION Pulse	t _{LOW}		Vio = 1.2 V	210	_	_	ns	

(2) SPI timings

- All timings are applied both to 4-wire and 3-wire SPI.
- To reduce external noise in High-Z state, we recommend the following;
 - In 4-wire mode, SDO terminal is pulled up to Vio via the resister.
 - In 3-wire mode, SDI terminal is pulled up to Vio via the resister.
 - e.g.) Rpullup = $3.6k\Omega$ @Vio=1.8V.



Items	Symbol	Condition	Min.	Тур.	Max.	Units	Remark
SCK frequency	f_spi		-	-	10	MHz	
SCK low pulse	t_low_sck		40	-	-	ns	
SCK high pulse	t_high_sck		40	-	-	ns	
SDI setup time	t_setup_sdi		20	-	-	ns	
SDI hold time	t_hold_sdi		20	-	-	ns	
SDO output delay	t_delay_sdo	Cb = 25 pF, Vio = 1.62 V min	-	-	30	ns	
SDO output delay	I_Uelay_Sub	Cb = 25 pF, Vio = 1.2 V min	-	-	40	ns	
CSB setup time	t_setup_csb		40	-	-	ns	
CSB hold time	t_hold_csb		40	-	-	ns	
CSB_HI time	t_csb_hi		100	_	_	ns	

Reset Function

The sensor is capable of resetting the operation with "Asynchronous Reset Terminal (RST pin)".

The procedure is as follows: Input high voltage to RST pin. (100 μ s \geq)

Turn off (input low voltage) and wait 10 ms.

Reset sequence



Recommended conditions of communication

In case that this sensor and other sensors are connected with a common bus line, if you use this sensor at a communication speed more than 400 kbit/s, after finishing the communication with other sensors, we recommend to provide 1 ms or more waiting time before starting the communication with this sensor in order to ensure a stable communication (see diagram below).

Typical connection diagram

Example of communication



Packaging

Configuration of shipment

Packaging	Embossed Carrier Tape
Quantity	3,500 pcs / 1 reel 1 reel / 1 Interior box Max. 20 Interior boxes / 1 exterior box
Reel	180 mm dia.
Insert method	see below

Note: Specification of taping & reel comply with JIS C 0806-3 (IEC 60286-3).

Taping

Emboss pitch 4 mm type & tape width 8 mm type.



2SMPB-02E

Reel



Individual packaging



Recommended Soldering Method

Soldering method

Air Reflow (Max. 2 times)

■ Condition of Temperature

Max. 260°C, within 40 seconds

Recommended Soldering Method

Temperature profile conditions of reflow soldering should set the temperature condition as shown in the below table and then confirm that actual conditions are met them in the table.



Item	Preheating (T1 to T2, t1)	Soldering (T3, t2)	Peak value (T4)
Terminal	150°C to 200°C	> 217°C	260°C
	60 sec to 180 sec.	60 sec to 150 sec.	20 sec to 40 sec.

• Since the pressure sensor chip is exposed to atmosphere, cleaning fluid shall not be allowed to enter inside the sensor's case.

• We recommend that it should be used the recommended mounting PAD dimensions for the land pattern.

Safety Precautions

Precautions for Correct Use

Handling

- (1) Only air can be used as pressure media on the product directly. It is prohibited to use pressure media including corrosive gases (e.g. organic solvents gases, sulfur dioxide and hydrogen sulfide gases), fluid and any other foreign materials.
- (2) The products are not water proof. The product shall be kept dry in use excluding the sensor port.
- (3) The product shall not be used under dew-condensing conditions. Frozen fluid on sensor chips may cause fluctuation of sensor output and other troubles.
- (4) The product shall be used within rated pressure. Usage at pressure out of the range may cause breakage.
- (5) The product may be damaged by static electricity. Charged materials (e.g. a workbench and a floor) and workers should provide measures against static electricity, including ground connection.
- (6) The product shall not be dropped and handled roughly.
- (7) The product shall not be used under dusty or damp condition.
- (8) Do not wash the print circuit board after the pressure sensor is mounted using solvent. It may cause a mal-function.
- (9) Please connect the sensor terminals according to the connection diagram.
- (10) The product shall not be used under high-frequency vibration including ultrasonic wave.
- (11) This product uses the elastic adhesive for bonding the lid, so do not add excessive stress to the lid.
- (12) If soldering is not fit, then this product may catch fire or get hot.
- (13) There is a possibility that the peripheral circuit board or some electronic part generates heat while driving this product. Please handle with care.
- (14) Do not tear down this product.
- (15) Please do not use the sensor after following case;
 - excessive shock added to the terminal of the sensor
 - the sensor lid decapped
 - the sensor dropped
- (16) If you use other conditions described in this document, please check yourself in advance.

Environmental conditions for transport and storage

- (1) The product shall not be kept with corrosive gases (e.g. organic solvents gases, sulfur dioxide and hydrogen sulfide gases).
- (2) The products are not water proof. The product shall be kept dry during storage.
- (3) The outer box strength may be degraded depending on the storage conditions. Please use the product in order.
- (4) For this product, please keep away from direct sunlight or ultraviolet rays.
- (5) The product shall be kept in appropriate conditions of temperature and humidity.
- (6) The product shall not be kept under dusty or damp condition.

Warranty and Limited Warranty

Definition

The definition of terms used in these Terms and Conditions are as follows:

- (1) Usage conditions: Usage conditions, rating, performance, operating environment, handling instructions, cautions, prohibited use, etc. of Omron products described in specifications, documentations or manuals.
- (2) Customer application: Application of Omron products by customers which include embedding and/or using Omron products in their parts/components, electronic substrates, devices, equipment or systems manufactured by customers.
- (3) Fitness: (a) performance, (b) non-infringement of third-party intellectual property, (c) compliance with laws and regulations and (d) conformity to various standards.

Caution on Descriptions

Attention is required to the following points on descriptions in specifications.

- (1) Rated values and performance values are the product of tests performed for separate single conditions, including but not limited to temperature and humidity. It is not intended to warrant rated values and performance values for multiple combined conditions.
- (2) Reference data are provided for reference only. Omron does NOT warrant that Omron products work properly at all time in the range of reference data.
- (3) Application examples are provided for reference only. Omron does NOT warrant the Fitness of Omron products under such application.
- (4) Omron may discontinue the production of Omron products or change the specifications of them for the purpose of improving such products or other reasons entirely at its own discretion.

Precautions

Please be aware of and accept the following when you introduce or use Omron products:

- (1) Please use Omron products in compliance with usage conditions including rating and performance.
- (2) Please confirm fitness of Omron products in your application and use your own judgment to determine the appropriateness of using them in such application. Omron shall not warrant the fitness of Omron products in customer application.
- (3) Please confirm that Omron products are properly wired and installed for their intended use in your overall system.
- (4) When using Omron products, please make sure to (i) maintain a margin of safety vis-à-vis the published rated and performance values, (ii) design to minimize risks to customer application in case of failure of Omron products, such as introducing redundancy, (iii) introduce system-wide safety measures to notify risks to users, and (iv) conduct regular maintenance on Omron products and customer application.
- (5) Omron products are designed and manufactured as general-purpose products for use in general industrial products. They are not intended to be used in the following applications. If you are using Omron products in the following applications, Omron shall not provide any warranty for such Omron products.
 - (a) Applications with stringent safety requirements, including but not limited to nuclear power control equipment, combustion equipment, areas areas and other applications that could cause danger/harm to people's body and life.
 - (b) Applications that require high reliability, including but not limited to supply systems for gas, water and electricity, etc., 24 hour continuous operating systems, financial settlement systems and other applications that handle rights and property.
 - (c) Applications under severe condition or in severe environment, including but not limited to outdoor equipment, equipment exposed to chemical contamination, equipment exposed to electromagnetic interference and equipment exposed to vibration and shocks
 - (d) Applications under conditions and environment not described in specification
- (6) In addition to the applications listed from (a) to (d) above, Omron products are not intended for use in automotive applications (including two wheel vehicles). Please do NOT use Omron products for automotive applications. Please contact Omron sales staff for products for automotive use.

Warranty Terms and Conditions

The terms and conditions for warranty of Omron products are as follows:

- (1) Warranty period: One year after the purchase.
- (2) Coverage: Omron will provide free replacement of the malfunctioning Omron products with the same number of replacement/alternative products
- (3) Exceptions: Omron will not cover Omron products under its warranty if the cause of the malfunction falls under any of the following.(a) Usage in a manner other than the original intended use for the Omron product.
 - (b) Usage outside of the usage conditions.
 - (c) Cause which could not have been foreseen with the level of science and technology at the time of shipping from Omron.
 - (d) Causes originating from other than Omron or Omron products (including force majeure such as but not limited to natural disasters).

Limitation of Liability

The warranty set out in these Terms and Conditions is the whole and sole liability for Omron products. There are no other warranties, expressed or implied. Omron and the distributors of Omron products are not liable for any damages which may arise from or be related to Omron products.

Export Controls

Customers of Omron products shall comply with all applicable laws and regulations of other relevant countries with regard to security export control, when exporting Omron products and/or technical documents or providing such products and/or documents to a non-resident. Omron may not provide customers with Omron products and/or technical documents should they fail to comply with such laws and regulations.

Please check each region's Terms & Conditions by region website.

OMRON Corporation Electronic and Mechanical Components Company

Regional Contact Americas https://www.components.omron.com/ Asia-Pacific https://ecb.omron.com.sg/ Korea https://www.omron-ecb.co.kr/

Europe http://components.omron.eu/ China https://www.ecb.omron.com.cn/ Japan https://www.omron.co.jp/ecb/

© OMRON Corporation 2017-2018 All Rights Reserved.

In the interest of product improvement, specifications are subject to change without notice.

Cat. No. A260-E1-02 0318(1017)(O)